## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO. : 7,038,505 B2 APPLICATION NO.: 10/750558

Page 1 of 1

**DATED** INVENTOR(S) : May 2, 2006 : Cole et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## Figure 1

[Ref no.] 24 "...PULSE CLCOK..." should read --...PULSE CLOCK...--

## Column 3

Line 17, "...earlier, 16 latch banks 26..." should read --...earlier, 16 [no bold] latch banks

Line 45, "...via 16 corresponding..." should read --...via 16 [no bold] corresponding...--.

## Column 5

Line 32, "...a glitch design may..." should read --...a glitch design 168 may...-.

Line 63, "...StbP 204 and StbN 206..." should read --...StbP214 and StbN 216...-.

Signed and Sealed this

Thirty-first Day of July, 2007

JON W. DUDAS Director of the United States Patent and Trademark Office